


Diagnostic Result



Truck 

www.truckmela.net

☎ 09-43-43-95-55



Diagnostic Result

Vehicle

ACTROS 930.0 - 934.3

Control unit

FR

Current fault codes

Code	Text	No.	Status	
17071	Learning error with splitter ratio	0	CURRENT	
13430	Clutch travel sensor has -//-,  - or  +.	0	CURRENT	
13635	Clutch position sensor not within permissible range	0	CURRENT	
15154	Solenoid valve Engine brake 2 has -//-.	0	CURRENT	



Vehicle

ACTROS 930.0 - 934.3

Control unit

FR

Clutch pedal is learned.



Vehicle


ACTROS 930.0 - 934.3

Control unit


FR

Clutch pedal is learned.

Clutch travel



Clutch travel when new



Vehicle

ACTROS 930.163

Control unit

MR

Current fault codes

Code	Text	No.	Status	
10310	Crankshaft position sensor, signal too low	1	CURRENT	



After the problem is solved

Vehicle

ACTROS 930.163

Control unit

FR

Current fault codes

Code	Text	No.	Status
	No fault code present		

Vehicle

ACTROS 930.163

Control unit

MR

Current fault codes

Code	Text	No.	Status	
10310	Crankshaft position sensor, signal too low	1	CURRENT	