


Diagnostic Result



Truck 

www.truckmela.net

☎ 09-43-43-95-55



Diagnostic Result

Vehicle

ACTROS 930.0 - 934.3

Control unit

FR

Current fault codes

Code	Text	No.	Status	
17071	Learning error with splitter ratio	0	CURRENT	
13430	Clutch travel sensor has $-//-$, $\neg \neg -$ or $\neg \neg +$.	0	CURRENT	
13635	Clutch position sensor not within permissible range	0	CURRENT	
15154	Solenoid valve Engine brake 2 has $-//-$.	0	CURRENT	



Vehicle

ACTROS 930.0 - 934.3

Control unit

FR

Clutch pedal is learned.




Vehicle

ACTROS 930.0 - 934.3

Control unit

FR





After the problem is solved

Vehicle

ACTROS 930.0 - 934.3

Control unit

FR

Current fault codes

Code	Text	No.	Status
	No fault code present		