

Diagnostic Result



www.truckmela.net

Vehicle

ACTROS 930.163

Control unit

MR

Current fault codes

Code	Text	No.	Status	
10310	Crankshaft position sensor, signal too low	1	CURRENT	



Vehicle

ACTROS 930.163

Control unit

FR

Current fault codes

Code	Text	No.	Status	
13430	Clutch travel sensor has $-//-, \square \neg -$ or $\square \neg +$.	0	CURRENT	
13430	Clutch travel sensor has $=//-, \square \neg -$ or $\square \neg +$.	1	CURRENT	



ESC



F1



F3



STOP

F5



F6



F8



F9



F11



Vehicle

ACTROS 930.163

Control unit

FR

Clutch pedal is learned.



Vehicle

ACTROS 930.163

Control unit

FR

Clutch pedal is learned.

