


5-1-2 COCKPIT PANELS



CAPTAIN INSTRUMENT PANEL

CENTER INSTRUMENT PANEL

CO-PILOT INSTRUMENT PANEL


# 4 ON JA8106 & ON

TE FLAP OUT BD  
TE FLAP IN BD

# 5 ON (200B) AIRPLANES



FLAPS LIMIT (IAS)	
1 - 275 KN	20 - 231 KN
5 - 250 KN	25 - 205 KN
10 - 236 KN	30 - 180 KN
	130 - 160 (KN) ALT ON

PILOTS' INSTRUMENT PANELS




- \* 1 SWITCH DECALED INOP IS NOT INSTALLED ON JA8104 & ON
- \* 2 BEFORE END OF 1971, PANEL WILL BE MODIFIED
- \* 3 EXIT LIGHTS SWITCH IS NOT INSTALLED ON JA8104 & ON


PILOTS' OVERHEAD PANEL




PILOTS' CONTROL STAND - FWD & CENTER



PILOTS' CONTROL STAND - AFT



- # 1 DIODE NOT INSTALLED ON JA 8104 & ON
- # 2 PANEL INSTALLED ON JA 8104 & ON
- # 3 WEIGHT & BALANCE SYSTEM NOT INSTALLED ON JA 8106 & ON



F/E'S PANEL - UPPER & CENTER

