

Diagnostic Result



Truck 

www.truckmela.net

☎ 09-43-43-95-55

Vehicle

ACTROS 930.163

Control unit

MR

Current fault codes

Code	Text	No.	Status
	No fault code present		

Vehicle

ACTROS 930.163

Control unit

FR

Current fault codes

Code	Text	No.	Status	
03130	Coolant switch B6 or air filter monitoring sensor B7 is defective and/or one of the lines has   - or   +.	0	CURRENT	
13635	Clutch position sensor not within permissible range	0	CURRENT	
03130	Coolant switch B6 or air filter monitoring sensor B7 is defective and/or one of the lines has   - or   +.	1	CURRENT	



Vehicle

ACTROS 930.163

Control unit

FR

Clutch pedal is learned.



Vehicle

ACTROS 930.163

Control unit

FR

Clutch pedal is learned.

