

## Attachment B: Barn/Material Images

Images of the Littlerock Yellow Barn: Materials salvaged from deconstruction of this barn are available.





Image of structural system – all posts, beams, ties and braces to be deconstructed and available as salvage material.





Image of post-beam connections.





Detail of post-beam connection, showing round-log purlins in roof structure.



Detail showing connection of purlins to side wall plates, along with side wall posts and diagonal braces. All structural framing to be deconstructed and available for salvage.