


Diagnostic Result



Truck 

www.truckmela.net

☎ 09-43-43-95-55



Diagnostic Result

Vehicle

ACTROS 930.163

Control unit

MR

Current fault codes

Code	Text	No.	Status
	No fault code present		

Vehicle

ACTROS 930.163

Control unit

MR

Smooth running control: correction value

Cylinder 1	000.10 %
Cylinder 2	-000.33 %
Cylinder 3	000.31 %
Cylinder 4	-001.87 %
Cylinder 5	000.99 %
Cylinder 6	000.80 %

Wait until the actual values of the correction for smooth idle control are correctly displayed.

The correction values of the smooth idle control are zeroed by pressing key F5 if the engine is switched off.



F1



START

F5



F11



After the problem is solved

Vehicle

ACTROS 930.163

Control unit

MR

Smooth running control: correction value

Cylinder 1	000.45 %
Cylinder 2	000.07 %
Cylinder 3	000.28 %
Cylinder 4	-001.29 %
Cylinder 5	000.50 %
Cylinder 6	000.00 %
Wait until the actual values of the correction for smooth idle control are correctly displayed.	
The correction values of the smooth idle control are zeroed by pressing key F5 if the engine is switched off.	